


Scope of Work:

Over the lifetime of buildings taller than 80 ft. in height, the City of Chicago Building Department requires building owners to submit reports which document the results of cyclical hands-on exterior wall “Critical Examinations”. Visual “Ongoing Inspections” are also required intermittently between Critical Examinations.

HAG provides thorough and competitive Critical Examination Reports and Ongoing Inspection Reports to building owners for their properties, including those listed below for past clients. Our services include standard on-site high-resolution photography & up-close testing of building elements, as well as the use of proprietary digital imaging equipment. These methods provide clients the exact amounts and locations of any building distress onto accurate building elevations for the preparation of our reports. Experience with this work allows HAG to efficiently strategize methods to control the quality and costs of the investigation and any immediate repair work that may be required as a result.



1325 N Astor Condominium, Chicago



5617-19 S. Dorchester Cooperative, Chicago



901 South Plymouth Court Condominium, Chicago



5201 South Cornell Condominium, Chicago



Watergate Condominium, Chicago



6925-35 S. Crandon, Chicago